

## WARNING

**KEEP OUT OF REACH OF CHILDREN  
READ ENTIRE LABEL BEFORE OPENING**



**CHEMSEARCH**®

# CHELADE™

## POLYMERIC RUST CONVERTER

**One-step process halts existing rust  
and retards future rusting with a durable  
protective barrier. One litre covers up  
to 12 square metres.**

**Net Contents 950 ml**

**CHEMSEARCH AUSTRALIA  
5-9 RALPH STREET, ALEXANDRIA,  
NSW 2015 AUSTRALIA. PHONE (02) 693 5077**

© 1993 NCH CORPORATION — exclusive licensee NCH AUSTRALIA PTY. LIMITED  
A.C.N. 000 809 318

- \* **STOPS RUST** — chemically converts existing rust into a moisture-free black protective coating.
- \* **RETARDS FUTURE RUSTING** — advanced polymeric formula forms an oxidation-resistant coating.
- \* **EASY TO USE** — just brush, roll or spray on the surface to be treated.
- \* **EXCELLENT PRIMER** — may be painted over without further surface preparation.
- \* **ONE-STEP PROCESS** — eliminates acidizing, sandblasting, grinding and scraping.
- \* **NON-FLAMMABLE** — water based emulsion contains no solvents.
- \* **LONG SHELF LIFE** — may be stored for up to one year.

### DIRECTIONS FOR USE

- \* Stir well before using.
  - \* If surface is to be exposed to humidity, steam or water allow CHELADE to cure at least 3-7 days before top coating. Use solvent based top coat.
  - \* Keep container tightly closed when not in use.
- Apply when temperature 10°C — 38°C. Avoid application when water exposure is expected within 6 hours of application. Apply liberally to clean dry surface using brush, roller or airless spray gun. Do not clean down to bright metal. Before using spray gun, strain product through cheesecloth. After a few minutes a black coating will form over rusted areas only. A second coat may be required if black colour uneven, or for extreme environmental conditions. If product is stored in cold conditions it may separate or thicken. Before using, warm to room temperature and stir thoroughly. Do not return unused product to original container. Clean tools immediately with detergent and water.

Dries to a tack-free surface in 15-30 minutes. For outdoor and maximum indoor performance apply a top coat. Allow 24 hours between coats, but sometimes up to 5 days in hot and humid conditions.

### SAFETY DIRECTIONS

Avoid contact with skin and eyes. If skin contact occurs, wash thoroughly with water. If in eyes, flush with water for 15 minutes and see a doctor.

### FIRST AID

If poisoning occurs, contact a doctor or Poisons Information Centre. If swallowed, do NOT induce vomiting. Give a glass of water and consult a physician.