



**1000 SERIES
WARNINGS AND INSTRUCTIONS
REMOVE BY WEARER ONLY**

These WARNINGS and instructions are for your benefit - read them! Check with your supervisor or safety department to be sure these goggles are adequate for the eye hazard exposures of your job. **Failure to heed the WARNINGS can result in the risk of serious injury, including blindness.**

▲ WARNING

Do not use for protection against severe impact. These goggles have a polycarbonate lens which is impact resistant, but not unbreakable. Severe impact can break or dislodge the lens or pierce the frame.
Do not use for protection in "war" or "survival" games.

Contact with some chemical vapors or liquids can cause surface crazing of the lens and reduce its impact resistance. Replace the lens if crazing occurs, or when pits or scratches reduce vision.

Do not use for protection from harmful gases or vapors. These goggles are neither gas tight or liquid tight. If these are Chemical Splash Goggles, they protect the eyes only from direct contact with splashing liquids. **Do not use goggles with perforated frames for liquid splash protection.**

Humid conditions or heavy work effort can cause lens fogging and reduce vision. To avoid lens fogging, use a fog-free coated lens.

Do not use when performing torch burning or cutting, torch or electric (arc) welding, furnace or molten metal operations or other operations which are sources of infrared or ultraviolet radiation, or when using lasers. Neither the clear nor green lenses of these goggles will protect against harmful levels of IR or UV radiation, or against lasers.

To assure a tight fit:

1. Put on the goggles and assess the fit.
2. If the goggle frame does not touch your face around the frame's entire periphery, remove the goggles and tighten the headband by pulling a loose end.
3. If the goggle is too tight, remove the goggles and loosen the headband by grasping the loop where the headband folds and pulling it through the frame towards the lens leaving a loop protruding from the slot. Then grasp the headband and pull back thereby lengthening the headband.
4. Repeat the above process until you obtain a tight but comfortable fit.

Cleaning:

Clean with mild soap or detergent and warm water, rinse thoroughly to remove all traces of soap or detergent, and air dry, or pat dry with a soft, dry, lint free cloth.



North Safety Products
2000 Plainfield Pike
Cranston, RI 02921

Telephone 800 581 0444
Facsimile 800 572 6346

North Safety Products

26 Dansk Court
Toronto, Ontario
Canada M9W 5V8

Telephone 416 675 2810
Facsimile 416 675 6898